Step 1: pick the part

Step 2: select the material

Step 3: pick three points on the parts

Step 4: save the key word file

Write out a keep word file. For example test.k

Run test.k with the file launch manager or drop to the run batch file.

Read in results: (same window from BlankSize/one-step)

You can also open the d3plot file for result viewing, mfpre/fringe contour/thickness/FLD